

No.30 of 2023 Victoria Channel beacons 9, 15 & 18 not synchronised

Mariners are advised that the following lateral mark beacons are not synchronised with others in Victoria Channel:

Name	Characteristic	Latitude	Longitude
Victoria Channel No. 9	Q (3)G 6s	54 39.627N	005 50.877W
Victoria Channel No. 15	Fl.G.3s	54 38.350N	005 52.465W
Victoria Channel No.18	(Q(2)R.6s8M	54 37.969N	005 52.687W

Port Operations Belfast Harbour Captain K. G. Allen Harbour Master