

# Belfast Harbour

## NOTICE TO MARINERS

No. 2 OF 2021

### Fairway buoy AIS and RACON – Temporary outage

Mariners are advised of a temporary outage of the AIS and RACON on the Fairway buoy in position; 54° 42.32'N 005° 42.29'W

- AIS ('Belfast Fairway' MMSI # 992351003)
- RACON (G)

This notice will be considered automatically withdrawn once repairs to the AIS and RACON have been effected.

The Iso 4s light continues to function.

